

GREGORY S. BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

Minerals Inspection Report

Reviewed P17

07/15/2014 Report Date: Mine Name: Torrey Buff South Mine Status: Permit Number: S/055/0022 Active Operator Name: Quality Building Stone 07/10/2014 Permit Fees: Paid Inspection Date: Inspector(s): Wayne Western Inspection Time: **Bond Amount:** \$14,000 Attendee(s): John Reay (BLM) Lyman (employee) Weather: **Bond Escalation:** 01/12/2009 Inspection Purpose: Routine inspection 05/22/2013 Prior Inspection: **Conclusions and Recommendations** The Operator needs to post additional bond. Evaluated & Commented Enforcement **Elements of Inspection** Permits, Revisions, Transfer, Bonds X Permit fee has been paid, change status from suspended to active 2. Public Safety (shafts, adits, trash, signs, highwalls) X There are highwalls on site. The highwalls are approximately 8 feet tall. 3. Protection of Drainages/Erosion Control **Deleterious Material** There was trash on site. In addition there were two large blue barrels with fuild in them. The Operator should place the large barrels in a spill prevention facility. Roads (maintenance, surfacing, dust control, safety) Reclamation

Inspector	S	Signature	::
-----------	---	-----------	----

Soils Revegetation

Other

CC:

7.

8.

9. 10.


File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M055-Wayne/S0550022-HansenTorreyBuff/inspections/Insp070102014.pdf

The Operator has requested an on site meeting to discuss reclamation as a means to reduce the bond.



Backfilling/Grading (trenches, pits, roads, highwalls, shafts)

Mine: S/055/0022 Inspected: 07/10/2014





Mine: S/055/0022 Inspected: 07/10/2014




Load out area.



Dozer working area.



Highwalls



Working area - note tire and bucket

